

Basic Turning Tool List

1. Dust Mask and Face Shield, Safety Glasses, or Goggles
2. Spindle Roughing Gouge 3/4" or 1 1/4"
3. 3/8" or 1/2" Spindle Gouge
4. Parting Tool 1/4" or less
5. 3/8" side ground Bowl Gouge ("U" shaped flute not "V" shaped)
6. 3/4" Round Nose Scrapper
7. 3/8" traditional ground Bowl Gouge ("U" shaped flute) *
8. 1/16" Parting Tool *
9. 3/4" Square End Scrapper *

* Optional

Stay away from "Turning Sets" , the price may look attractive, but you'll be better served by purchasing quality individual tools as you need them.